

Sungrow Power Supply Co., Ltd. Add.: No.1699, Xiyou Rd., New & High Technology Industrial Develop Zone, Hefei, P.R. China. Zip: 230088 Web: <u>www.sungrowpower.com</u> E-mail: info@sungrow.cn Tel: +86 551 65327834 Fax: +86 551 65327856

To whom it may concern:

Sungrow hereby declares the following as regards the Rate of Chance of Frequency (RoCoF) and Vector Shift (VS) techniques for islanding detection and disconnection purposes in PV inverters installed in the UK:

| SG20KTL-M | |
|-----------|---|
| SG30KTL-M | |
| SG36KTL-M | |
| SG50KTL-M | |
| SG33CX | These models feature neither RoCoF nor VS. |
| SG40CX | |
| SG50CX | |
| SG110CX | |
| SG250HX | |
| SG60KTL | RoCoF/VS not present (for firmware versions |
| | dated June 2017 onwards). |
| | |
| | RoCoF/VS functionality can be manually |
| | deactivated (for firmware versions dated prior to |
| | June 2017) |

Hefei, P.R. China

5 January 2021

支里

Sean Li System Solution Manager of EMEA team Sungrow Power Supply Co., Ltd.

SUNGROW Company